




The sides marked with a wide black border must be placed properly against the reference areas to ensure that the holes are located accurately



2

The sides marked with a wide black border must be placed properly against the reference areas to ensure that the holes are located accurately





The sides marked with a wide black border must be placed properly against the reference areas to ensure that the holes are located accurately